

# **ZPure<sup>™</sup> Glass PolyGas II Purifiers** with Compression Fittings





# **Warnings**

Warnings must be read carefully and understood. Improper use of this product can cause harm or death to personnel and damage to property!



Wear eye protection and use caution when working with pressurized systems.

Maximum pressure rating is noted in table below.

When using a high-pressure gas source overpressure protection must be provided.

Do not open filter, even after use.

Do not use with supply gas H<sub>2</sub>O concentration greater than 0.1%. Contains molecular sieve which may become very hot in contact with liquid water. Do not use with liquids.

Do not expose the protective outer plastic tube to solvents.


Do not use without the protective outer plastic tube in place.

Special precautions might be required when using hydrogen or hazardous gases. Consult local regulations and your company's safety procedures.

### **Product Numbers**

Size	1/8" Brass	1/4" Brass	1/8" SS	1/4" SS	Maximum Pressure
Glass 46 cc Filters	202318-B	202319-B	202318-SS	202319-SS	11 bar / 160 psi





## Filter Setup and Use

Installation for Compression Fittings

- Check the package contents for damage. Contact your supplier if any items are damaged or missing.
- 2. The ZPure filter is delivered in the active state, filled with helium. It is ready for use, but it is recommended that the trap be purged with the gas to be purified.
- 3. For the best connections, start with freshly-cut tubing in the gas line. 1/8" nuts should be turned 3/4 turn past finger tight. 1/4" nuts should be turned 1-1/4 turns past finger tight.
- 4. To connect in-line, remove the end plugs from both ends of the filter, then attach the inlet end of the trap to the gas line.
- 5. While the end plugs are removed from the trap during installation, a small amount of air will diffuse into the adsorbent. As long as the trap is attached to the gas line within a few minutes, the loss of adsorbing capacity will be negligible.
- 6. Attach the outlet end of the trap.
- 7. While maintaining a low purge rate of 10 to 30 cc/min, purge the entire system until a total of 1 to 2 liters of gas has been flushed through.
- 8. Leak check all connections.



Trajan Scientific Americas Inc 2601 Technology Drive, Louisville, KY 40299, USA Tel: 502 491 6300

Fax: 502 491 3390 usa@trajanscimed.com



# Recycling

Please contact CRS for information regarding recycling and reconditioning gas purifier products.

© Trajan Scientific Americas Inc 09/2022 995210 \_RevB

